Machinefabriek Goudkuil Apeldoorn B.V.
Europaweg 200
7336 AR Apeldoorn
The Netherlands

Telephone: 055-533 20 23
E-Mail: info@goudkuil.com
Website: www.goudkuil.com

Visual Inspection Report

Previous Project, Kannegiesser Ironer

Index

1.0 Visual Overview, Rebuilt Kannegiesser Ironer Line 2
1.1 Overview of the Stripped Frame 2
1.2 Frame with Rolls Frontside View 2
1.3 Frame with Rolls Backside View 3
1.4 The new Thick Chest Upgrade 3
1.5 External Frontside View 4
1.6.1 External Backside, Lefthand View 4
1.6.2 External Backside, Righthand View 5
2.0 Visual Overview, Internal Mechanism 6
2.1 Installed New Chest 6
2.2 Installed Roll and New Springs 6
2.3 Brand New Drive Motor 7
3.0 Visual Overview, Controls and Electronics 8
3.1 Brand New Control Panel 8
3.2 Completely Rebuilt Control Panel Electronics & Internal Electronics 8
3.3.1 Completely Rebuilt Internal Electronics, Detailed 9
3.3.2 Completely Rebuilt Internal Electronics, Detailed 9
4.0 Visual Overview, Miscellaneous 10
4.1 Various Parts 10
4.2 Box of Parts, Detailed 10

1.0 Visual Overview, Rebuilt Kannegiesser Ironer Line

1.1 Overview of the Stripped Frame

1.2 Frame with Rolls Frontside View

1.3 Frame with Rolls Backside View

1.4 The new Thick Chest Upgrade

1.5 External Frontside View

1.6.1 External Backside, Lefthand View

1.6.2 External Backside, Righthand View

2.0 Visual Overview, Internal Mechanism

2.1 Installed New Chest

2.2 Installed Roll and New Springs

2.3 Brand New Drive Motor

3.0 Visual Overview, Controls and Electronics

3.1 Brand New Control Panel

3.2 Completely Rebuilt Control Panel Electronics & Internal Electronics

3.3.1 Completely Rebuilt Internal Electronics, Detailed



3.3.2 Completely Rebuilt Internal Electronics, Detailed

4.0 Visual Overview, Miscellaneous

4.1 Various Parts

4.2 Box of Parts, Detailed

40017
T-Nadeln
Stahl vernickelt
51 x 1,2 mm
500 Stück